

Eclipse Aerospace Publication Index



**Updated
October 2021**

Published By
Eclipse Aerospace, Inc.
3520 Spirit Drive SE
Albuquerque, New Mexico 87106
U.S.A.

© 2021 Eclipse Aerospace, Inc. (EAI). All rights reserved. No part of this publication may be reproduced, stored in a retrieval system, displayed, modified, distributed or transmitted in any form or by any means, electronic, mechanical, photocopying, recording or otherwise without the express prior written permission of the copyright holder.

These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. These commodities, technology or software are intended for use only in the End User's country. An export license from the U.S. Department of Commerce may be required before these products can be re-exported, transferred, transshipped on a non-continuous voyage, or otherwise disposed of in any other country, either in their original form or after being incorporated into an end item. Diversion of this end-item or its use contrary to any applicable U.S. government license or to U.S. law is prohibited.

Purpose

The Eclipse Aerospace Publications Index provides the current revision level/date of each publication or CD.

Flight Publications



Description	Part Number	Current Revision	Current Revision Date	FAA Approval Date
Standard Configuration				
Airplane Flight Manual (AFM)	06-100106	04	12/13/2007	12/13/2007
Temporary Revisions				
	06-100106-10	04	9/22/2008	-
	06-100106-13	04	6/12/2008	-
	06-100106-14	04	6/12/2008	-
	06-100106-15	04	9/3/2008	-
	06-100106-16	04	9/3/2008	-
	06-100106-17	04	12/9/2008	-
	06-100106-18	04	3/10/2010	-
	06-100106-19	04	5/18/2011	-
	06-100106-20	04	12/21/2018	-
	06-100106-21	04	6/19/2019	-
Quick Reference Handbook (QRH)	06-100107	03	12/13/2007	-
Flight Checklist Card	06-100110	n/a	12/13/2007	-
Performance Enhanced (EET) Configuration				
Airplane Flight Manual (AFM)	06-121654	001	1/28/2008	1/28/2008
Temporary Revisions				
	06-121654-12	001	3/10/2010	-
	06-121654-13	001	5/18/2011	-
	06-121654-14	001	12/21/2018	-
	06-121654-15	001	5/19/2019	-
Quick Reference Handbook (QRH)	06-121655	001	1/28/2008	-
Temporary Revisions				
	06-121655-TR10	001	3/10/2010	-
Flight Checklist Card	06-121656	-	1/28/2008	-
AVIO NG Configuration				
Airplane Flight Manual (AFM)	06-122204	04	7/23/2012	7/23/2012
Temporary Revisions				
	06-122204-TR16	4	11/9/2012	-
	06-122204-TR17	4	11/20/2012	-
	06-122204-TR18	4	12/20/2012	-
	06-122204-TR19	4	1/14/2013	-
	06-122204-TR20	4	3/13/2014	-
	06-122204-TR21	4	11/25/2013	-
	06-122204-TR22	4	2/5/2013	-
	06-122204-TR23	4	2/21/2013	-
	06-122204-TR25	4	10/18/2018	-
	06-122204-TR27	4	2/19/2014	-
	06-122204-TR28	4	5/21/2015	-
	06-122204-TR30	4	9/27/2016	-
	06-122204-TR33	4	12/21/2018	-
	06-122204-TR34	4	6/19/2019	-
Quick Reference Handbook (QRH)	06-122205	04	7/23/2012	-
Temporary Revisions				
	06-122205-TR016	04	11/9/2012	-
	06-122205-TR017	04	4/7/2014	-
	06-122205-TR018	04	9/27/2016	-

Description	Part Number	Current Revision	Current Revision Date	FAA Approval Date
Flight Checklist Card	06-122206	D	5/28/2012	-
Eclipse SE / Total Eclipse Plus / Eclipse 500 Plus Configuration				
Airplane Flight Manual (AFM)	06-123844	01	9/18/2015	9/18/2015
Temporary Revisions				
	06-123844-TR02	1	3/9/2016	3/9/2016
	06-123844-TR03	1	3/29/2016	3/29/2016
	06-123844-TR04	1	9/27/2016	-
	06-123844-TR05	1	10/21/2016	-
	06-123844-TR06	1	10/26/2016	10/26/2016
	06-123844-TR07	1	8/16/2017	8/16/2017
	06-123844-TR08	1	7/14/2017	-
	06-123844-TR09	1	8/15/2017	8/15/2017
	06-123844-TR10	1	12/21/2018	12/20/2018
	06-123844-TR11	1	6/19/2019	6/25/2019
Quick Reference Handbook (QRH)	06-123845	01	10/21/2015	-
Temporary Revisions				
	06-123845-TR01	01	12/14/20015	-
	06-123845-TR02	01	1/31/2018	-
Flight Checklist Card	06-123846	B	10/21/2015	-
Eclipse 550™ Configuration				
Airplane Flight Manual (AFM)	06-123841	Original Issue (OI)	6/2/2014	6/2/2014
Temporary Revisions				
	06-123841-TR01	OI	2/3/2015	2/3/2015
	06-123841-TR02	OI	4/3/2015	4/3/2015
	06-123841-TR04	OI	12/8/2015	12/8/2015
	06-123841-TR05	OI	3/14/2016	3/14/2016
	06-123841-TR06	OI	3/25/2016	3/25/2016
	06-123841-TR07	OI	9/27/2016	-
	06-123841-TR08	OI	10/21/2016	-
	06-123841-TR09	OI	8/16/2017	8/16/2017
	06-123841-TR10	OI	7/14/2017	-
	06-123841-TR11	OI	8/15/2017	8/15/2017
	06-123841-TR12	OI	12/20/2018	12/20/2018
	06-123841-TR13	OI	6/19/2019	6/25/2019
Quick Reference Handbook (QRH)	06-123842	Original Issue	6/2/2014	-
Flight Checklist Card	06-123843	A	7/10/2014	-
Rescue Chart				
Eclipse Jet Aircraft Rescue Crew Chart	06-122427-001	C	5/1/2014	-
AFM Supplements				
Standby Attitude Indicator	06-121770-01	Original Issue	4/20/2007	4/20/2007
Cabin Refreshment Cabinet	06-121770-02	Original Issue	4/28/2008	4/28/2008
Standby Attitude Indicator (AI-804)	06-121770-04	Original Issue	11/20/2008	11/20/2014
Michelin Bias Ply Tires	06-121770-05	Original Issue	3/6/2009	12/22/2009
Engine Fire Extinguishing Canister	06-121770-06	Original Issue	6/20/2011	6/20/2011
Anti-Skid Braking System (ABS)	06-121770-07	02	9/29/2014	2/3/2015
Integrated Flight Management System (IFMS) 2.7	06-121770-08	Original Issue	2/24/2014	IS&S doc 12/26/2013

Description	Part Number	Current Revision	Current Revision Date	FAA Approval Date
Integrated Flight Management System (IFMS) 2.08	06-121770-09	Original Issue	7/28/2014	10/15/2014
Brazilian AFMS, Supplement BR-01	06-122953-BR-01	01	11/10/2014	11/13/2014
EASA Supplement (Third Attitude Indicator)	06-122953-EASA01	Original Issue	12/11/2008	12/11/2008
European Commercial Operations	06-122953-EUOPS01	01	12/14/2010	5/21/2010
Bilingual Placards - Turkey	06-122953-TC-01	Original Issue	6/24/2010	6/24/2010

Maintenance Publications



Description	Part Number	Current Revision	Current Revision Date	FAA Approval Date
AMM - EA500 Configuration				
EA500 Aircraft Maintenance Manual (AMM)	06-117751	020	2/24/2017	2/24/2017
EA500 AMM Temporary Revisions				
	06-117751-TR04-999	020	8/13/2015	8/13/2015
	06-117751-TR04-5	020	11/13/2019	11/20/2019
	06-117751-TR05-21	020	5/24/2021	-
	06-117751-TR06-1	020	5/29/2018	-
	06-117751-TR21-5	020	2/12/2016	-
	06-117751-TR21-5	020	10/29/2019	-
	06-117751-TR22-4	020	5/20/2020	-
	06-117751-TR24-12	020	9/9/2019	-
	06-117751-TR25-3	020	5/29/2018	-
	06-117751-TR27-8	020	2/1/2019	-
	06-117751-TR30-7	020	9/12/2019	-
	06-117751-TR30-8	020	3/4/2020	-
	06-117751-TR31-5	020	8/19/2019	-
	06-117751-TR32-11	020	8/18/2020	-
	06-117751-TR34-21	020	9/30/2020	-
	06-117751-TR35-1	020	12/16/2019	-
	06-117751-TR52-1	020	8/31/2017	-
	06-117751-TR52-2	020	4/24/2019	-
	06-117751-TR73-2	020	8/19/2019	-
	06-117751-TR80-1	020	9/5/2019	-
Supplements				
EASA EA500 AMM Supplement	06-122713	002	3/12/2012	4/12/2012
EA500 AMM, Supplement (ABS)	06-124051	002	7/10/2015	-
AMM SUPPLEMENT, IFMS 2.5 + (Contains IS&S: 1D-10186 and 1D-08571)	06-124576	01	2/26/2014	-
AMM - Eclipse 550 Configuration				
Eclipse 550 Aircraft Maintenance Manual (AMM)	06-123838	01	2/24/2017	2/24/2017
Eclipse 550 AMM Temporary Revisions				
	06-123838-TR00-1	1	11/22/2017	-
	06-123838-TR04-999	1	8/13/2015	8/13/2015
	06-123838-TR04-1	1	7/11/2017	7/11/2017
	06-123838-TR04-5	1	11/13/2019	11/20/2019
	06-123838-TR05-14	1	4/24/2019	-
	06-123838-TR21-3	1	10/29/2019	-
	06-123838-TR21-4	1	5/20/2020	-
	06-123838-TR22-2	1	5/20/2020	-
	06-123838-TR23-1	1	5/4/2016	-
	06-123838-TR24-6	1	11/16/2016	-
	06-123838-TR24-8	1	9/9/2019	-
	06-123838-TR25-2	1	1/29/2016	-
	06-123838-TR27-3	1	3/16/2016	-
	06-123838-TR27-4	1	2/1/2019	-
	06-123838-TR28-2	1	1/15/2016	-
	06-123838-TR30-4	1	9/12/2017	-
	06-123838-TR31-3	1	8/19/2019	-

Description	Part Number	Current Revision	Current Revision Date	FAA Approval Date
	06-123838-TR32-6	1	8/18/2020	-
	06-123838-TR34-10	1	1/27/2020	-
	06-123838-TR34-12	1	2/5/2021	-
	06-123838-TR35-1	1	12/16/2019	-
	06-123838-TR52-2	1	4/24/2019	-
	06-123838-TR73-2	1	8/19/2019	-
	06-123838-TR80-1	1	9/5/2019	-
Supplements				
EASA EA550 AMM Supplement	06-123838-EASA	A	3/14/2016	3/14/2016
IPC - EA500 Configuration				
EA500 Illustrated parts Catalog (IPC)	06-117752	31	7/10/2020	-
IPC - Eclipse 550 Configuration				
Eclipse 550 Illustrated parts Catalog (IPC)	06-123839	06	5/15/2020	-
WDM - EA500 Configuration				
EA500 Wiring Diagram Manual (WDM)	06-117753	07	12/8/2008	-
Eclipse 500 WDM Temporary Revisions				
	06-117753-TR24-1	07	9/15/2013	-
	06-117753-TR24-2	07	9/13/2014	-
	06-117753-TR30-1	07	9/15/2013	-
	06-117753-TR30-2	07	2/25/2016	-
	06-117753-TR30-3	07	9/15/2018	-
	06-117753-TR30-4	07	12/21/2018	-
	06-117753-TR30-5	07	2/28/2019	-
	06-117753-TR30-6	07	2/28/2019	-
	06-117753-TR34-3	07	8/21/2018	-
	06-117753-TR34-4	07	9/26/2019	-
WDM - Eclipse 550				
Eclipse 550 Wiring Diagram Manual (WDM)	06-123840	2	8/16/2019	-
Eclipse 550 WDM Temporary Revisions				
	06-123840-TR23-1	2	10/11/2021	-
Maintenance Documents, All Configurations				
Avio Maintenance Computer (AMC) Reference Manual CF-18	20-120999-2001	02	10/25/2007	-
Avio Maintenance Computer (AMC) Reference Manual CF-19	20-121927-2001	01	9/14/2007	-
Fault Isolation Manual (FIM)	06-117754	05	11/6/2017	-
Illustrated Tool and Equipment Manual (ITEM)	06-117756	08	11/1/2017	-
EA500 Structural Repair Manual (SRM)	06-117755	005	11/15/2017	-
Wiring Repair Manual (WRM)	06-120792	3	9/15/2011	-
MISC				
EA500 Dispatch Deviations Guide	06-122591	3	8/29/2018	-
Master Minimum Equipment List (MMEL)	Refer to FAA site			
Eclipse Jet Aircraft Rescue Chart	06-122427-001	May 2014	5/29/2014	-
Non-Destructive Inspection Manual (NDI)	06-123429	00	9/24/2012	-

Service Bulletins



SB Number	Rev	SB Type	Title	Issue Date	Effectivity
EA500 Service Bulletins					
SB 500-04-001	C	Optional	Configuration Definition For Aircraft To Be Exported In EASA Countries	4/15/2016	Model EA500 aircraft 000001 to 000262, and 000266 to 000267 to be registered in countries which accept the Type Certificate validated by the European Aviation Safety Agency (EASA).
SB 500-04-002	B	Optional	Configuration Definition For Aircraft To Be Exported to Brazil	7/24/2012	000001 - UP, All Eclipse Jets to be registered in Brazil under authority of the Agência Nacional De Aviação Civil – Brasil (ANAC). Avionics configuration: Avio IFMS 2.0
SB 500-04-003	D	Optional	Configuration Definition For Aircraft To Be Exported to United Arab Emirates	5/3/2012	000001 - UP, All Eclipse Jets to be registered in UAE under authority of the General Civil Aviation Authority – (GCAA). Avionics configuration: Avio IFMS 2.0
SB 500-04-004	B	Optional	Configuration Definition For Aircraft To Be Exported to Pakistan	7/1/2014	000001 - UP, All Eclipse Jets to be registered in Pakistan under authority of the Pakistan Civil Aviation Authority – (PCAA). Avionics configuration: Avio IFMS 2.0 / 2.7
SB 500-04-005	B	Optional	Configuration Definition For Aircraft To Be Exported to South Africa	7/1/2014	000001 - UP, All Eclipse Jets to be registered in South Africa under authority of the South African Civil Aviation Authority – (SACAA). Avionics configuration: Avio IFMS 2.0 / 2.7
SB 500-04-006	J	Optional	Extending Aircraft Service Life Limits	3/14/2017	000001 to 000038 when modified by SB 500-99-001, Performance Enhancement and Drag Reduction Modification and in compliance with Section 3.
SB 500-04-007	A	Optional	One Time Extension of 48 Month Calendar Inspection Interval	3/7/2016	Aircraft Serial Numbers 0001-0262, 0266, and 0267
SB 500-11-001	A	Alert	Placard Modification – Max Aft Baggage Weight	3/9/2007	000001

SB Number	Rev	SB Type	Title	Issue Date	Effectivity
SB 500-11-002	A	Recommended	Placard Inspection and Replacement	7/14/2008	000195 - 000201
SB 500-11-003	N	Optional	Aircraft Registration Markings and Avionics Settings for International Registered Aircraft	3/3/2016	000001 - UP
SB 500-11-004	K	Optional	Fire Proof Identification Plate for International Registered Aircraft	2/22/2016	000001 - UP
SB 500-11-005	K	Optional	Bilingual Placards for International Registered Aircraft	10/25/2016	000001 - UP
SB 500-11-006	A	Optional	Placard, Chock Mains	8/12/2014	000001 to 000262, 000266 and 000267
SB 500-21-001	B	Mandatory	Outflow Valve Static Line Security	12/15/2009	000001 - 000291
SB 500-21-003	B	Mandatory	Integrated Twin Pack Compressor Pallet Assembly (ITPCA) Inspection/Repair	9/7/2012	000001 - 000300
SB 500-21-004	C	Optional	VORE Seal Installation	4/9/2012	000001 - 000300
SB 500-21-005	B	Recommended	Forward and Aft Evaporator Stepper Motor Actuator Replacement	11/14/2012	000001 - 000300
SB 500-21-006	A	Mandatory	Cockpit Engine Bleed Air Feed Duct Replacement	1/6/2013	000001 - 000300
SB 500-21-007	A	Mandatory	Outflow Valve and Flow Control Valve Recall	3/27/2014	000022, 000037, 000054, 000057, 000077, 000150, and 000192
SB 500-21-008	B	Mandatory	GDCA Gap Inspection	3/27/2015	000001-000262, 000266, & 000267

SB Number	Rev	SB Type	Title	Issue Date	Effectivity
SB 500-21-009	A	Mandatory	Gearbox Venting Improvement	5/29/2015	000001-000262, 000266, 000267
SB 500-23-001	A	Alert	Avio NG KTR 2280 Multi-Mode Digital Radio Upgrade	1/16/2008	000105
SB 500-23-002	A	Optional	KTR 2280 Multi-Mode Digital Radio Upgrade	5/28/2008	000105-000112, 000116-000119, 000121-000122 and 000125-000265
SB 500-23-003	D	Optional	Sat Phone Installation	11/15/2011	000001 - 000265 Post SB 500-99-005 and 000266 - UP
SB 500-23-004	B	Recommended	Audio Mixer Upgrade	4/10/2013	000001-000104, 000113-000115, 000120, 000123-000124, Post SB 500-99-002 and 000105-000112, 000116-000119, 000121-000122, 000125 - UP
SB 500-24-001	A	Alert	Aft Power Distribution Center (APDC) Insulation Modification	5/31/2007	000001 - 000016
SB 500-24-002	A	Alert	Battery Bus Contactor and External Power	8/15/2007	000001-000012
SB 500-24-003	D	Optional	In Seat Power Supply	3/20/2012	000001 - 000104, 000113 - 000115, 000120, and 000123 - 000124 Post SB 500-99-002 000105 - 000112, 000116 - 000119, 000121 - 000122, and 000125 -
SB 500-24-004	C	Mandatory	Aft Power Distribution Center Replacement	11/9/2011	000001 - 000300
SB 500-24-008	B	Mandatory	External Power Receptacle Inspection	10/28/2015	000001 to 000262, 000266 and 000267
SB 500-25-001	A	Alert	Crew Seat, Adjustment Cable Modification	3/28/2007	000001 and 000003
SB 500-25-004	A	Optional	Seat, Armrest Installation	4/30/2010	000001 - 000198
SB 500-25-005	A	Optional	Refreshment Cabinet Installation	4/30/2008	000001 - 000300
SB 500-25-006	C	Optional	Sun Visor Installation	3/14/2016	000001 - UP

SB Number	Rev	SB Type	Title	Issue Date	Effectivity
SB 500-25-009	B	Mandatory	Center Forward Floor Panel Modification	11/9/2011	000105 - 000112, 000116 - 000119, 000121 - 000122, 000125 - 000300
SB 500-25-010	B	Mandatory	ELT Mounting Tray Replacement	6/25/2015	000001 to 000262, 000266, 000267, and 550-0263 to 550-0265, 550-0268 to 550-02820, 550-0282 to 550-0284
SB 500-25-011	C	Mandatory	Glareshield Replacement & Bonding Verification	3/6/2019	000004, 000006, 000013, 000018, 000020 to 000022, 000027, 000033, 000039, 000040, 000046, 000059, 000064, 000071, 000091, 000095, 000105, 000113, 000115, 000117, 000120, 000128, 000129, 000133, 000140, 000145, 000156, 000159, 000167, 000183, 000199, 000211, 000212, 000220, 000221, 000227, 000233, 000235, 000236, 000267.
SB 500-26-001	D	Mandatory	Phostrex Fire Extinguisher Cartridge (FEC) Replacement	12/3/2012	000001 - 000300
SB 500-26-002	A	Mandatory	Engine Fire Detection Loop Cap Seal Inspection	11/22/2010	000001 - 000260
SB 500-26-003	A	Mandatory	Fire Suppression Tubing Inspection	7/19/2012	000001 - 000300
SB 500-27-001	B	Recommended	Elevator Hinge Cover Inspection/Modification	9/12/2008	000039 - 000054
SB 500-27-004	C	Alert	Aileron Joint Assembly Inspection and Replacement	7/2/2014	000001 - 000278
SB 500-27-005	A	Alert	Outboard Flap Actuator Fitting Replacement	8/1/2008	000240
SB 500-27-006	C	Mandatory	Rudder Spring Replacement	9/12/2013	000001-000194 Post SB 500-99-004 and 000195 - 000300
SB 500-27-008	B	Mandatory	Flight Control Functional Check Verification	6/8/2013	000001 - 000261

SB Number	Rev	SB Type	Title	Issue Date	Effectivity
SB 500-28-001	A	Alert	Fuel Gauging Probes Replacement	7/20/2007	000001 - 000023
SB 500-28-002	B	Alert	Engine Start Pump Bonding and Grounding	2/7/2008	000039 - 000121, 000123 and 000124
SB 500-30-001	B	Recommended	Wing Deice Boot Upgrade	11/16/2007	000001 - 000073, 000079, 000080, and 000085
SB 500-30-002	C	Recommended	Inspection and Treatment of Wing and Tail De-ice Boots Installation for Surface Corrosion	9/17/2014	000001 - 000262, 00266, 000267 550-0263 to 550-0265, 550-0268 to 550-0280, and 550-0282 to 550-0284
SB 500-31-001	D	Alert	Diagnostic Storage Unit (DSU) Upgrade	6/7/2007	000001 - 000014
SB 500-31-002	A	Alert	Electronic Flight Instrument System (EFIS) Upgrade	4/5/2007	000001 - 000013
SB 500-31-004	A	Recommended	Diagnostic Storage Unit (DSU) Software Update (2.8.05)	6/15/2007	000001 - 000038
SB 500-31-005	A	Recommended	Aircraft Computer System (ACS) and Digital Flaps System (DFS) Software Upgrade	6/13/2007	000001 and 000003
SB 500-31-006	B	Recommended	Aircraft Computer System (ACS) Software Update to 4.4.52	1/10/2008	000001 - 000038
SB 500-31-007	A	Alert	Multiunction Display (MFD) Software Upgrade	10/26/2007	000001 - 000069

SB Number	Rev	SB Type	Title	Issue Date	Effectivity
SB 500-31-008	B	Recommended	Diagnostic Storage Unit (DSU) Electrical Connector Upgrade	5/16/2008	000001 - 000049
SB 500-31-009	B	Optional	Diagnostic Storage Unit (DSU) Spares	11/8/2007	000001 - 000089
SB 500-31-011	A	Recommended	Electronic Flight Instrument System (EFIS) 1.1 Software Update	3/31/2008	000001 - 000104, 000113 - 000115, 000120 and 000123 - 000124 Post SB 500-99-002, and 000105 - 000112, 000116 - 000119, 000121 - 000122 and 000125 - UP
SB 500-31-012	A	Recommended	DSU 3.0.012 Software Update	5/23/2008	000027, 000055, 000056, 000057, 000066, 000109, 000110, 000112, 000129, 000132, 000133, 000141, 000171, 000183
SB 500-31-013	A	Recommended	DSU 3.0.50 Software Update	11/21/2008	000001 - 000265
SB 500-31-014	A	Mandatory	Aircraft Computer System (ACS) Software Update to 4.6.04	2/15/2011	000001 - 000104, 000113 - 000115, 000120, 000123, and 000124
SB 500-31-015	D	Required	EFIS 1.3 Software Update	1/14/2009	000001 - 000104, 000113 - 000115, 000120, 000123 - 000124 Post SB 500-99-002, and 000105 - 000112, 000116 - 000119, 000121 - 000122, 000125 - 000265
SB 500-31-016	A	Optional	Instrument Panel, Left - Red Electrical Switches	3/29/2010	000001 - 000324
SB 500-31-018	C	Recommended	Aircraft Computer System (ACS) Software Update to 5.3.06	11/9/2011	000001 - 000008, 000010 - 000050, 000052, 000054 - 000300
SB 500-31-019	B	Mandatory	Aircraft Computer System (ACS) Software Update to 5.1.06	3/13/2013	000001 - 000104, 000113 - 000115, 000120 and 000123 - 000124 when modified by SB 500-99-002, Avionics Upgrade to Avio NG Configuration AND NOT modified by SB 500-99-005, Avionics Upgrade To Avio NG + 1.5 Configuration.

SB Number	Rev	SB Type	Title	Issue Date	Effectivity
SB 500-31-020	A	Mandatory	DSU 3.0.54 Software Update	3/29/2010	000001 - 000260
SB 500-31-022	C	Mandatory	DSU 3.0.64 Software Update	11/9/2011	000001 - 000300
SB 500-31-023	B	Mandatory	Center Switch Panel (CSP) Inspection Replacement	10/10/2012	000001 - 000260 NOT modified by SB 500-99-004 or SB 500-99-005
SB 500-31-024	B	Recommended	Integrated Flight Management System (IFMS) Upgrade	2/20/2012	Eligible EA500 aircraft with, or upgraded to, the Avio NG 1.5 configuration
SB 500-31-026	B	Mandatory	Software Configuration Update	3/27/2013	All Avidyne configured aircraft and all Avio NG 1.0 configured aircraft. 000001 - 000265 Pre SB 500-99-005
SB 500-31-027	A	Recommended	MFD Firmware Update	9/1/2015	000001-000262, 000266-000267
SB 500-32-001	A	Recommended	Hydraulic Fitting Replacement, Brake Line, Main Landing Gear	1/29/2007	000001 and 000002
SB 500-32-006	B	Alert	Landing Gear Emergency Extension Inspection and Rigging	10/17/2007	000001 - 000062
SB 500-32-008	B	Required	Master Cylinder Inspect/Replace	8/20/2008	000001 - 000110
SB 500-32-009	A	Recommended	Landing Gear Inspection and Application of Corrosion Inhibiting Compound	7/3/2008	000001 - 000276
SB 500-32-010	B	Recommended	Bias Ply Tire Installation	12/15/2009	000001 - 000276
SB 500-32-011	B	Mandatory	Wheel Speed Transducer (WST) Connector Inspection	3/20/2015	000001 to 000262 and 000266 to 000267

SB Number	Rev	SB Type	Title	Issue Date	Effectivity
SB 500-32-012	C	Mandatory	Main Landing Gear Trunnion Inspection	11/13/2015	000001 to 000262, 000266 to 000267
SB 500-32-013	A	Optional	Anti-Skid Brake System Installation for Aircraft Equipped with AVIO IFMS 2.08	3/18/2015	000001 to 000262, 000266 to 000267
SB 500-32-014	D	Mandatory	Left Hand MLG Trunnion Repair/Replacement	11/13/2015	000001 to 000262, 000266 to 000267
SB 500-32-015	D	Mandatory	Right Hand MLG Trunnion Repair/Replacement	11/13/2015	000001 to 000262, 000266 to 000267
SB 500-32-016	B	Recommended	Wheel Speed Transducers (WST) Inspection & Repair	9/2/2020	0001-0262, 0266-0267 - Post MB 500-32-002.
SB 500-33-001	A	Recommended	Landing Light Ballast Location Inspection/Re work	12/15/2009	000001 - 000299
SB 500-34-001	A	Alert	Pitot/Angle Of Attack Probes Upgrade/Retrofit	2/7/2007	000001 - 000004, 000006, and 000007
SB 500-34-002	E	Optional	Optional Installation of a Third Attitude Indicator	10/3/2012	000001 - 000104, 000113 - 000115, 000120 and 000123 - 000124
SB 500-34-003	A	Recommended	Attitude Heading Reference System (AHRS) Upgrade to P/N 8350-0150-16	4/19/2007	000001
SB 500-34-004	B	Mandatory	Standby Pitot/Static Probe Upgrade	2/6/2013	000001 - 000033
SB 500-34-005	B	Alert	Pitot/Angle-of-tack (AOA) System Upgrade	7/10/2007	000001 - 000064

SB Number	Rev	SB Type	Title	Issue Date	Effectivity
SB 500-34-006	A	Recommended	Digital Flaps System Software Upgrade	5/31/2007	000002
SB 500-34-008	C	Optional	Stormscope Installation	11/3/2011	Avio NG + 1.5 (Production Aircraft 266 and UP or Aircraft modified with SB 500-99-005)
SB 500-34-009	A	Optional	JRC Weather Radar Installation	4/25/2008	000055 - 000104, 000113 - 000115, 000120, and 000123 - 000124
SB 500-34-010	B	Optional	Terrain Awareness Warning System (TAWS) Installation	5/2/2008	000001 - 000050 and 000052-UP
SB 500-34-011	C	Optional	Traffic Advisory System (Skywatch) Installation	10/27/2010	000001 - UP
SB 500-34-013	A	Optional	Automatic Direction Finding (ADF) System Installation	4/11/2008	000001 - 000050 and 000052
SB 500-34-014	C	Optional	Distance Measurement Equipment (DME) Installation	5/29/2008	000001 - 000050 and 000052
SB 500-34-015	E	Optional	3rd Attitude Source Installation	11/19/2014	Avio NG (Production Aircraft 0105 through 0112, 0116 through 0119, 0121, 0122 and 0124 through 0262 or Aircraft modified with SB 500-99-002)
SB 500-34-016	B	Optional	Dual Mode S Diversity Transponder Installation	3/29/2010	000001 - UP
SB 500-34-017	A	Recommended	Spectralux GPS-SBAS Receiver Replacement	9/29/2008	000001 - 000008, 000010 - 000050, 000052 - 000253
SB 500-34-018	D	Optional	Installation of Garmin GNS 430 and GTX 330	8/29/2012	000009 and 000053
SB 500-34-019	C	Alert	Pitot/AOA Probe Inspection/Test	8/20/2008	000001 - 000189

SB Number	Rev	SB Type	Title	Issue Date	Effectivity
SB 500-34-020	B	Optional	Standby Attitude, Altitude and Airspeed Package	5/10/2010	000001 - 000300
SB 500-34-021	A	Required	Static Drain Line Inspection for Protective Caps	11/6/2008	000001 - 000258
SB 500-34-023	A	Optional	Nose Ballast Replacement with Weather Radar	5/13/2010	000055 - 000104, 000113 - 000115, 000120 and 000123 - 000124
SB 500-34-024	B	Optional	G400W 3.30/3.2 Software Update	11/9/2011	000001 - 000265 in the Avio NG +1.5 configuration
SB 500-34-025	A	Mandatory	Harco Pitot Probe Software Upgrade	9/10/2014	000001 to 000262, post SB 500-99-004 and 000266 to 000267
SB 500-34-027	A	Mandatory	Pitot / AOA Probe Flange Heater	12/21/2018	000001 to 000262, 000266, 000267
SB 500-34-028	B	Mandatory	iS&S GPS Week Rollover Correction (iFMS 2.7.8)	4/30/2019	000001 to 000262, 000266, 000267 with iFMS version 2.7.8.
SB 500-34-029	A	Mandatory	iS&S GPS Week Rollover Correction (iFMS 2.0.8/2.5.2)	4/17/2019	000001 to 000262, 000266, 000267 with iFMS version 2.0.8 or 2.5.2.
SB 500-35-001	B	Mandatory	Crew Oxygen Mask Replacement	1/15/2015	000001 - 000258
SB 500-35-002	B	Optional	40 Cu. Ft. Oxygen Cylinder and Co-Pilot's Quickon Oxygen Mask Installation	4/23/2012	000001 - UP
SB 500-39-001	A	Recommended	Wire Harness Inspection and Repair - Battery Area	9/13/2011	000001 - 000300
SB 500-52-001	B	Alert	Door Lock Handle Replacement	11/14/2007	000001 - 000071

SB Number	Rev	SB Type	Title	Issue Date	Effectivity
SB 500-52-007	A	Recommended	Lower Cabin Door Step Cable Restraint	9/30/2008	000001 - 000073
SB 500-52-008	B	Alert	Main Landing Gear-Lower Door Aero Seal Modification	2/6/2008	000001 - 000104
SB 500-52-009	B	Optional	Cabin Door Proximity Switch Modification	11/1/2010	000001 - 000324
SB 500-52-010	B	Mandatory	Passenger Door Lock Pin O-Ring Replacement	5/15/2019	000001-000262, 000266-000267
SB 500-53-001	A	Recommended	Filler Removal – Upper and Lower Fuselage Skins	2/16/2007	000001
SB 500-53-003	A	Recommended	Corrosion Prevention	11/11/2008	000001 - 000208, 000212
SB 500-53-005	B	Recommended	Nose Panel and Radome Sealing	11/21/2011	000001 - 000399
SB 500-53-007	A	Optional	Structural Component Replacement	12/21/2011	000072
SB 500-53-008	B	Mandatory	Lower Wing to Body Fairing Drainage	2/13/2012	000001 - 000300
SB 500-53-009	B	Recommended	External Stowage Compartment Door Inspection and Modification	10/5/2017	000001-000262, 000266-000267
SB 500-54-001	A	Recommended	Pylon Trailing Edge Seal Modification	3/10/2017	000039 - 000044
SB 500-54-002	B	Recommended	Engine Tail Cone Primer	2/1/2010	000001 - 000189
SB 500-54-003	A	Recommended	Leading Edge Skin Assembly Fire Extinguisher Sight Glass Replacement	1/3/2012	000001 - 000300

SB Number	Rev	SB Type	Title	Issue Date	Effectivity
SB 500-54-004	A	Recommended	VORE Lower Louver Skin Drainage	1/18/2013	000001 - 000300
SB 500-54-005	A	Recommended	Right Pylon Inspection and Repair	12/19/2019	000001-000262, 000266-000267
SB 500-55-001	B	Alert	Horizontal Stabilizer Inspection	5/18/2007	000001 - 000011, and 000014
SB 500-56-001	A	Recommended	Windshields and Cockpit Side Windows Upgrade	10/1/2007	000001 - 000073
SB 500-56-002	A	Recommended	Windshield Resistive Strip Installation	9/8/2010	000001 - 000265
SB 500-57-001	B	Recommended	Wing Attachment Fittings Modification	2/21/2007	000001
SB 500-57-002	A	Optional	Forward Wing Attach Link - Alternate Part	2/21/2007	000001
SB 500-57-003	B	Alert	Wing – Electrical Bonding Rework	3/23/2007	000001 and 000003
SB 500-57-004	A	Alert	Fuel System - Electrical Bonding Verification – Wing Station 185	4/24/2007	000001 - 000004, and 000006 - 000010
SB 500-57-005	B	Alert	Wing Tip Tank Fastener Inspection/Repair	9/7/2007	000039 - 000046
SB 500-57-006	A	Optional	Flap Gurney Tab Speed Restriction Placard Removal	3/11/2008	000001 - 000104
SB 500-57-007	B	Alert	Fuel Filler Adapter - Lightning Protection - Inspection/Re work	10/23/2007	000039 - 000062
SB 500-57-008	D	Optional	Flap Actuator Upgrade	3/24/2016	000001 - 000239
SB 500-57-011	B	Mandatory	Wing Attach Point Inspection	3/1/2012	000001 - 000300

SB Number	Rev	SB Type	Title	Issue Date	Effectivity
SB 500-57-012	A	Mandatory	Overbraid Inspection	3/24/2016	000001 to 000239
SB 500-57-013	A	Recommended	Wing Corrosion Inspection	6/24/2020	000001-000262, 000266-000267
SB 500-71-001	A	Alert	Starter Generator Power/Ground Grommet Rework	5/2/2008	000001 - 000134
SB 500-71-002	B	Mandatory	LH/RH ACS Grommet Inspection/Re work	9/9/2010	000001 - 000134
SB 500-72-001	C	Recommended	Engine Oil Filler and Sight Glass Replacement	7/10/2014	000001 - 000038
SB 500-73-002	B	Alert	Left Engine - Fuel Control Harness Modification	6/28/2007	000001 - 000003, and 000006 - 000012
SB 500-73-004	B	Mandatory	FADEC Inspection/Replacement	4/25/2012	000001 - 000260
SB 500-76-001	C	Alert	Throttle Lever Test	1/7/2015	000001 through 000038 pre SB 500-99-001 and 000039 through 000262, 000266, and 000267, pre SB 500-76-002
SB 500-76-002	B	Mandatory	FADEC Software Upgrade	8/26/2014	000001 - 000038, Post SB 500-99-001
SB 500-99-001	D	Recommended	Performance Enhancement and Drag Reduction Modification	6/27/2012	000001 - 000038
SB 500-99-002	H	Recommended	Avionics Upgrade To Avio NG Configuration	6/22/2012	000001 - 000104, 000113 - 000115, 000120, 000123, and 000124
SB 500-99-004	F	Recommended	Flight Into Known Icing (FIKI) Modification	9/14/2015	000001 - 000265
SB 500-99-005	D	Recommended	Avionics Upgrade To Avio NG + 1.5 Configuration	6/22/2012	000001 - 000008, 000010 - 000050, 000052, 000054 - 000265
SB 500SC-001	A	Alert	FADEC Software Modification	4/21/2007	000001 - 000038

SB Number	Rev	SB Type	Title	Issue Date	Effectivity
EA550 Service Bulletins					
SB 550-11-001	A	Optional	Placard, Chock Mains	2014-08-12	550-0263 to 550-0265, 550-0268 to 550-0280, and 550-0282 to 550-0284
SB 550-21-001	B	Mandatory	GDCA Gap Inspection	2015-03-27	550-0263 to 550-0265 and 550-0268 to 550-0278
SB 550-21-002	A	Mandatory	Gearbox Venting Improvement	2015-06-01	550-0263 through 550-0265, 550-0268 through 550-0280, 550-0282 through 550-0284 and 550-1001.
SB 550-24-002	B	Mandatory	External Power Receptacle Inspection	2015-10-28	550-0263 to 550-0265, 550-0268 to 550-0280 and 550-0282 to 550-0284
SB 550-25-001	B	Mandatory	Glareshield Replacement & Bonding Verification	2017-05-23	550-0263 to 550-0265, 550-0268 to 550-0278, and 550-1001
SB 550-25-002	A	Optional	Cabin Floor Panel Upgrade	2015-08-10	550-0271, 550-0274 to 550-0284 Post MB 500-25-003, and 550-1001
SB 550-31-001	A	Recommended	MFD Firmware Update	2015-09-01	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284, and 550-1001
SB 550-32-001	B	Mandatory	Wheel Speed Transducer (WST) Connector Inspection	2015-03-20	550-0263 to 550-0265, 550-0268 to 550-0280, and 550-0282 to 550-0284
SB 550-32-002	D	Mandatory	Main Landing Gear Trunnion Inspection	2015-12-01	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284, and 550-1001
SB 550-32-003	E	Mandatory	Left Hand MLG Trunnion Repair/Replacement	2015-12-01	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284, and 550-1001.
SB 550-32-004	E	Mandatory	Right Hand MLG Trunnion Repair/Replacement	2015-12-01	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284, and 550-1001.
SB 550-32-005	B	Recommended	Wheel Speed Transducers (WST) Inspection & Repair	2020-09-02	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284 and 550-1001 to 550-1013.
SB 550-34-001	A	Mandatory	Harco Pitot Probe Software Upgrade	2014-09-10	550-0263 to 550-0265, 550-0268 to 550-0280, and 550-0282 to 550-0284

SB Number	Rev	SB Type	Title	Issue Date	Effectivity
SB 550-34-006	A	Mandatory	Pitot / AOA Probe Flange Heater	2018-12-21	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284 POST MB 500-34- 025, and 550-1001 and up
SB 550-34-007	B	Mandatory	iS&S GPS Week Rollover Correction (iFMS 2.7.8)	2019-04-30	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284, 550-1001 and up with iFMS 2.7.8.
SB 550-52-001	B	Mandatory	Passenger Door Lock Pin O-Ring Replacement	2019-05-15	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284, 550-1001 and up.
SB 550-53-001	B	Recommended	External Stowage Compartment Door Inspection and Modification	2017-11-15	0263-0265, 0268-280, 0282-0284, 1001 - UP
SB 550-54-001	A	Recommended	Right Pylon Inspection and Repair	2019-12-19	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284, 550-1001 and up.
SB 550-55-001	A	Mandatory	Elevator Drain Hole Inspection	2015-06-02	550-0275 through 550-0278, and 550-1001
SB 550-57-001	B	Recommended	Wing Corrosion Inspection	2020-06-25	Aircraft Serial Numbers 550-0263 - 550-0265, 550-0268 - 550-0280, 550-0282 - 550-0284 and 001001 - UP
SB 550-80-001	A	Mandatory	Starter Generator TSO Label Correction	2017-04-18	See complete list in SB

Modification Bulletins



MB Number	Rev	MB Type	Title	Issue Date	Effectivity
EA500 Modification Bulletins					
MB 500-04-002	C	Optional	Configuration Definition For Aircraft To Be Exported To Brazil (ANAC)	3/12/2015	000001 to 000262, and 000266 to 000267 and 550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284
MB 500-04-003	A	Optional	Configuration Definition for Aircraft to be Exported to United Arab Emirates (GCAA)	10/27/2014	000001 - UP
MB 500-04-004	A	Optional	Configuration Definition for Aircraft to be Exported to Pakistan (PCAA)	10/27/2014	000001 - UP
MB 500-04-005	B	Optional	Configuration Definition For Aircraft To Be Exported to South Africa (SACAA)	5/29/2019	000001 - UP
MB 500-04-006	A	Optional	Configuration Definition for Aircraft to be Exported to Mexico (DGAC)	10/9/2014	000001 - UP
MB 500-04-007	B	Mandatory (Mandatory for all Eclipse Jets to be registered in the Republic of San Marino under authority of the San Marino Civil Aviation Authority (SMCAA))	Configuration Definition for Aircraft to be Exported to San Marino (SMCAA)	3/20/2019	000001 - UP

MB Number	Rev	MB Type	Title	Issue Date	Effectivity
MB 500-04-008	A	Optional	Configuration Definition for Aircraft to be Exported to Saudi Arabia (GACA)	10/9/2014	000001 - UP
MB 500-04-009	A	Optional	Configuration Definition for Aircraft to be Exported to The Isle of Man (United Kingdom's Commonwealth) CAA	10/9/2014	000001 - UP
MB 500-04-010	A	Optional	Configuration Definition For Aircraft To Be Exported To Australia (CASA)	10/31/2014	000001 - UP
MB 500-04-011	A	Optional	Configuration Definition For Aircraft To Be Exported To India (DGCA)	10/31/2014	000001 - UP
MB 500-04-012	A	Optional	Configuration Definition for Aircraft to be Exported to Togo (ANAC)	3/3/2015	000001 - UP
MB 500-04-013	D	Optional	Configuration Definition for Aircraft to be Exported to The States of Guernsey (CAA)	5/21/2019	All EA500 aircraft to be registered in The States of Guernsey under authority of The States of Guernsey Civil Aviation Authority (CAA).
MB 500-04-015	A	Optional	Configuration Definition for Aircraft to be Exported to Argentina (ANAC)	10/25/2016	000001 to 000262, and 000266 to 000267
MB 500-11-001	A	Optional	Total Eclipse Nameplate Installation	3/18/2014	000001 - 000262, and 000267
MB 500-11-002	A	Optional	Total Eclipse Plus Nameplate Installation	3/18/2014	000001 - 000262, and 000267

MB Number	Rev	MB Type	Title	Issue Date	Effectivity
MB 500-11-003	B	Mandatory	550 Nameplate Installation	12/13/2013	000266
MB 500-11-004	A	Optional	Eclipse SE Nameplate Installation	9/16/2015	000001 to 000262 and 000266, 000267
MB 500-20-001	B	Optional	Exterior Finish	7/16/2015	000280, 000282, 000283, and 000284
MB 500-20-002	A	Optional	Icephobic Coating Shape Change	8/28/2015	000001 to 000262 and 000266, 000267
MB 500-21-001	F	Optional	VCS Compressor Assembly Replacement	6/29/2015	000001 - 000262, Post SB 500-99-005, and 000266, 000267
MB 500-23-001	A	Optional	Multi ode Digital Radio (MMDR) Software Update	9/22/2014	000001 to 000262, 000266 and 000267, post SB 500-23-002
MB 500-24-002	A	Optional	USB Capable Outlet Upgrade	2/28/2014	000001 - 000262, 000266 - 000267, Post MB 500-24-006
MB 500-24-003	A	Recommended	Generator Control Unit (GCU) Modification	11/22/2013	000001 - 000300
MB 500-24-004	A	Recommended	Comm Jack Diode Cover Installation	11/21/2013	000001 - 000300
MB 500-24-005	C	Recommended	ECBU Configuration Update (rev. - 006)	5/6/2014	000001 - 000262, post SB 500-99-005 and 000266 - 000267
MB 500-24-006	B	Recommended	Power Supply Upgrade for In Seat Power Supply (ISPS) System	2/15/2016	000001 to 000262, 000266 to 000267, post MB 500-31-008, or MB 500-31-009
MB 500-24-008	D	Mandatory	External Power Receptacle Bonding Improvement	10/21/2015	000001-000262, 000266 and 000267
MB 500-25-001	B	Optional	Interiors Mod - Multi-Purpose Rail	11/13/2015	000263 - 000265, 000268 - 000300
MB 500-25-003	D	Optional	Premium Interior Replacement	1/24/2017	500-0001 to 500-0262, 500-0266, and 500-0267 post MB 500-56-001, MB 500-34-001, MB 500-31-003, MB 500-25-001, and MB 500-24-002.

MB Number	Rev	MB Type	Title	Issue Date	Effectivity
MB 500-25-004	B	Optional	Eclipse SE Seat Upgrade	1/18/2017	0001-0262, 0266, 0267
MB 500-25-005	A	Optional	Glareshield Modification - Nordam to PPG Compatibility	3/6/2019	000001 to 000262, 000266, and 000267
MB 500-31-001	B	Mandatory	BIO Software Update to Version 4.4	11/14/2012	000001 - 000300, Post SB 500-99-004
MB 500-31-002	B	Recommended	Instrument Panel Left (IPL) ELT Switch Guard Installation	9/8/2012	000001 - 000300
MB 500-31-003	G	Optional	Avio NG 2.5 Provisions	7/14/2014	000001 - 000300
MB 500-31-004	B	Recommended	Aircraft Computer System (ACS) Software Update to 5.5.06	5/25/2016	000001 to 000262, 000266 and 000267
MB 500-31-005	D	Recommended	Bio Software Update to Version 6.0	12/10/2019	000001 to 000262, 000266 and 000267
MB 500-31-006	H	Recommended	IFMS 2.5 Software Upgrade and SDU Install	9/27/2016	000001 to 000262, 000266 and 000267
MB 500-31-007	K	Recommended	IFMS 2.7 Equipment Upgrade	10/2/2019	000001-000262, Post SB 500-99-005, and 000266-000267
MB 500-31-008	F	Recommended	IFMS 2.08 Equipment Upgrade	2/15/2016	000001 to 000262, post SB 500-99-005 and 000266 to 000267
MB 500-31-009	D	Recommended	IFMS 2.06 to 2.08 Equipment Upgrade	2/15/2016	000001 - 000262, 000266, and 000267 post SB 500-31-024
MB 500-31-010	B	Recommended	Standby Display Unit (SDU) OFF - 03 to -05 Software Upgrade	1/9/2015	000001 to 000262 and 000266 to 000267
MB 500-31-011	C	Recommended	IFMS 2.5.1 to 2.5.2 Software Upgrade	2/25/2015	000001 through 000262, 000266, and 000267

MB Number	Rev	MB Type	Title	Issue Date	Effectivity
MB 500-31-012	A	Recommended	Aircraft Computer System (ACS) Software Update to 5.6.04	7/21/2015	000001-000262, 000266, 000267
MB 500-31-013	B	Recommended	IFMS 2.7 to 2.7.5 Software Upgrade	8/21/2015	0001-0262, 0266, 0267
MB 500-31-014	D	Recommended	Comm Jack Panel Modification, NCH Connector	12/14/2015	000001 through 000262, 000266, and 000267
MB 500-31-015	B	Recommended	ADS Out System (with Garmin GPS 400W)	7/17/2017	000001 to 000262 and 000266 to 000267
MB 500-31-016	B	Recommended	ADS Out (IFMS 2.8)	8/21/2017	000001 through 000262, 000266, and 000267
MB 500-31-017	B	Recommended	Aircraft Computer System (ACS) Software Update to 5.7.02	7/6/2017	000001 to 000262, 000266, and 000267
MB 500-31-018	A	Recommended	ADS OUT System (with Garmin GPS 400W)	11/21/2016	000250
MB 500-31-019	D	Recommended	iFMS 2.7.5 to 2.7.8 Software Upgrade	8/23/2017	000001 through 000262, 000266, and 000267
MB 500-31-020	B	Recommended	DSU 3.1.02 Software Update	9/28/2017	000001 through 000262, 000266, and 000267
MB 500-31-021	C	Recommended	iFMS 2.7.8 to 2.7.10 Software Upgrade	4/18/2019	000001 through 000262, 000266, and 000267, post MB 500-31-019.
MB 500-32-001	A	Recommended	Landing Gear Actuator Upgrade	11/28/2012	000001 - 000104, 000113 - 000115, 000120, 000123 - 000124, Post SB 500-99-002 and
MB 500-32-002	J	Optional	Anti-Skid Brake System Installation	8/18/2020	000001 - 000262, 000266 to 000267, Post MB 500-31-006
MB 500-32-003	D	Mandatory	ABS Pressure Switch and Harness Reroute	5/25/2016	000001 to 000262, 000266 to 000267,

MB Number	Rev	MB Type	Title	Issue Date	Effectivity
MB 500-32-004	C	Optional	Anti-Skid Brake System (ABS) Installation for IFMS 2.08 Aircraft	8/18/2020	000001 to 000262, 000266 to 000267 with IFMS 2.08
MB 500-33-001	A	Recommended	Wingtip Navigation Light Modification	7/21/2015	000001 to 000262, 000266 and 000267
MB 500-34-001	C	Recommended	Static System Tubing Upgrade	3/14/2017	000001 - 000300
MB 500-34-002	B	Optional	Structure Install - EVS	6/24/2015	000265
MB 500-34-003	C	Recommended	Options Rack and Harness	8/26/2014	000001 - 000262, 000266, 000267
MB 500-34-005	A	Optional	Automatic Direction Finding (ADF) System Installation	1/23/2015	000001 to 000262, 000266, and 000267
MB 500-34-006	A	Optional	Distance Measurement Equipment (DME) Installation	1/23/2015	000001 to 000262, 000266, and 000267
MB 500-34-007	A	Optional	Dual Mode S Diversity Transponder Installation	1/23/2015	000001 to 000262, 000266, and 000267
MB 500-34-008	A	Optional	ADS Out Provisions	1/28/2016	000001 to 000262, 000266, 000267
MB 500-34-025	H	Mandatory	Harco Pitot Probe Software Upgrade	8/11/2015	000001 - 000262, post SB 500-99-004 and 000266 - 000267
MB 500-34-027	E	Mandatory	Pitot / AOA Probe Flange Heater	8/21/2019	000001 to 000262, 000266, 000267
MB 500-34-028	G	Mandatory	Pitot/AOA Probe Flange Heater (Independent)	4/14/2020	000001 to 000262, 000266, 000267 with Avio NG 1.3, Avio NG 1.5 or Avio NG 1.7 or iFMS 2.08 or 2.5.2.
MB 500-34-030	E	Recommended	ADS OUT for IFMS 2.08/2.5.2 Aircraft Configuration	8/28/2019	Aircraft Serial Numbers: 000001 to 000262, 000266, 000267

MB Number	Rev	MB Type	Title	Issue Date	Effectivity
MB 500-34-031	B	Recommended	GTX33 Transponder Configuration Update and ADS OUT Fail Indicator Brightness	4/1/2019	000045, 000048, 000056, 000100, 000160, 000183, 000208 and 000260 modified by MB 500-34-030 - ADS Out for iFMS 2.08/2.5.2 Aircraft Configuration.
MB 500-56-001	E	Recommended	PPG Windshield Upgrade	3/6/2019	000001 - 000079, Post SB 500-56-001, or 000074 - 000262, 000266, 000267. With ACS 5.5.06 higher and EFIS 2.5 software or higher for compatibility with ACS 5.5.06
MB 500-76-001	B	Mandatory	FADEC Software Upgrade	8/19/2014	000001 - 000038, Post SB 500-99-001 and 000039 - 000262, 000266, 000267
MB 500-99-001	C	Optional	Collector Bulletin - Total Eclipse Plus™	12/14/2015	000001 - 000262, 000266, and 000267
MB 500-99-002	B	Optional	Collector Bulletin - Eclipse 500 Plus™	12/14/2015	000001 – 000262, 000266, and 000267
MB 500-99-003	B	Recommended	Collector Bulletin - Eclipse SEP	10/23/2017	000001-000262, 000266, 000267
MB 500-99-004	D	Optional	Collector Bulletin - Eclipse SE	10/23/2017	000001 to 000262, 000266, and 000267

MB Number	Rev	MB Type	Title	Issue Date	Effectivity
EA550 Modification Bulletins					
MB 550-04-001	C	Optional	Configuration Definition for Aircraft to be Exported to and Registered in EASA Member States	2/5/2016	EASA configuration requirements for the Eclipse 550 aircraft 550-0263 through 550-0265, 550-0268 through 550-0280, 550-0282 through 550-0284 which incorporate Eclipse FAA approved Modification Bulletin MB 550-99-001 and 550-1001 and UP.
MB 550-04-002	A	Optional	Configuration Definition for Aircraft to be Exported to Brazil (ANAC)	3/12/2015	ANAC configuration requirements for the Eclipse 550 aircraft 550-0263 through 550-0265, 550-0268 through 550-0280, 550-0282 through 550-0284 which incorporate Eclipse FAA approved Modification Bulletin MB 550-99-001 and 550-1001 and UP.
MB 550-04-013	B	Optional	Configuration Definition for Aircraft to be Exported to The States of Guernsey (CAA)	10/22/2015	The States of Guernsey (CAA) configuration requirements for the Eclipse 550 aircraft 550-0263 through 550-0265, 550-0268 through 550-0280, 550-0282 through 550-0284 which incorporate Eclipse FAA approved Modification Bulletin MB 550-99-001 and 550-1001 and UP.
MB 550-04-015	A	Optional	Configuration Definition for Aircraft to be Exported to Argentina (ANAC)	10/25/2016	ANAC configuration requirements for the Eclipse 550 aircraft 550-0263 through 550-0265, 550-0268 through 550-0280, 550-0282 through 550-0284 which incorporate Eclipse FAA approved Modification Bulletin MB 550-99-001 and 550-1001 and UP.
MB 550-20-001	B	Optional	Icepobic Coating Shape Change	9/27/2016	550-0263 to 550-0265, 550-0268 to 550-0280 and 550-0282 and up.
MB 550-20-002	A	Optional	Exterior Finish	1/22/2016	550-1002 and up
MB 550-23-001	A	Optional	Multi-Mode Digital Radio (MMDR) Software Update	9/22/2014	550-0263 to 550-0265, 550-0268 to 550-0280, and 550-0282 to 550-0284
MB 550-24-002	D	Mandatory	External Power Receptacle Bonding Improvement	10/28/2015	550-0263 to 550-0265, 550-0268 to 550-0280 and 550-0282 to 550-0284
MB 550-24-003	A	Recommended	ECBU Configuration Update (rev. - 006)	2/27/2020	550-1001 - UP

MB Number	Rev	MB Type	Title	Issue Date	Effectivity
MB 550-25-001	B	Optional	Eclipse Slim Seat Upgrade	1/10/2017	000263 to 000265, 000268 to 000280, 000282 to 000284, 550-1001 and UP.
MB 550-31-001	B	Recommended	Standby Display Unit (SDU) OFP - 03 to -05 Software Upgrade	1/9/2015	550-0263 to 550-0265, 550-0268 to 550-0280, and 550-0282 to 550-0284.
MB 550-31-002	A	Recommended	Aircraft Computer System (ACS) Software Update to 5.6.04	7/21/2015	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284, and 550-1001
MB 550-31-003	B	Recommended	iFMS 2.7 to 2.7.5 Software Upgrade	8/21/2015	550-0263 to 550-0265, 550-0268 to 550-0280, and 550-0282 to 550-0284
MB 550-31-004	D	Recommended	Comm Jack Panel Modification, NCH Connector	9/27/2016	550-0263 through 550-0265, 550-0268 through 550-0280, 550-0282 through 550-0284, and 550-1001.
MB 550-31-006	A	Recommended	ADS Out (IFMS 2.8)	8/17/2017	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284, 550-1001 and up
MB 550-31-007	B	Recommended	Aircraft Computer System (ACS) Software Update to 5.7.02	6/29/2017	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284, and 550-1001 and up
MB 550-31-008	C	Recommended	iFMS 2.7.5 to 2.7.8 Software Upgrade	7/14/2017	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284, 550-1001 and up
MB 550-31-009	B	Recommended	DSU 3.1.02 Software Update	9/28/2017	000263 to 000265, 000268 to 000280, 000282 to 000284, 550-1001 and up
MB 550-31-010	C	Recommended	iFMS 2.7.8 to 2.7.10 Software Upgrade	4/18/2019	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284, 550-1001 and up postMB 550-31-008.
MB 550-32-001	D	Mandatory	ABS Pressure Switch and Harness Reroute	4/3/2015	550-0263 to 550-0265, 550-0268 to 550-0280, and 550-0282 to 550-0284
MB 550-33-001	A	Recommended	Wingtip Navigation Light Modification	7/21/2015	550-0263 to 550-0265, 550-0268 to 550-0280, and 550-0282 to 550-0284

MB Number	Rev	MB Type	Title	Issue Date	Effectivity
MB 550-34-003	A	Optional	Automatic Direction Finding (ADF) System Installation	1/23/2015	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284, & 550-1001 and UP
MB 550-34-004	B	Optional	Distance Measurement Equipment (DME) Installation	4/3/2020	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284, & 550-1001 and UP
MB 550-34-005	B	Optional	Dual Mode S Diversity Transponder Installation	2/23/2015	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284, & 550-1001 and UP
MB 550-34-006	E	Mandatory	Pitot / AOA Probe Flange Heater	8/21/2019	550-0263 to 550-0265, 550-0268 to 550-0280, 550-0282 to 550-0284 POSTMB 500-34-025, and 550-1001 and up
MB 550-99-001	A	Optional	Collector Bulletin Eclipse 550	7/22/2014	550-0263 to 550-0265, 550-0268 to 550-0280, and 550-0282 to 550-0284

Service Information Letters (SIL)



Document Number	Subject	Effectivity	Applicability	Issue Date
SIL 04-0001	Structural Modifications Not Approved by Eclipse Aerospace	All	Aircraft Eligible for Extended Service Life Limit per SB 500-04-006	10/30/2013
SIL 04-0003	Alternative Method of Compliance for AD 2008-16-15	All	All	12/11/2014
SIL 04-0004	FAA Type Certificate Data Sheet (TCDS) Revision 20	All Aircraft	All Aircraft	8/1/2017
SIL 04-0005	Engine Fire Extinguisher Canister Component Limitation EASA Approval	All	All	1/14/2020
SIL 04-0006	Alternate Approved Aircraft Inspection Programs	All	All	7/7/2020
SIL 05-0001	Engine Control System Fault Interrogation	(500-) 000001-000300	Post SB 500-99-001 Aircraft	3/20/2013
SIL 05-0002	Secondary Outflow Valve Filter Replacement	All	All	4/5/2013
SIL 05-0003	Eclipse Aerospace Authorized Service Centers	All	All	4/28/2017
SIL 05-0004	Repetitive Inspection requirements for Aftermarket GPS Installations	All	Aircraft with Aftermarket GPS Installations	7/9/2014
SIL 05-0005	Replacement Times for Life-Limited Parts	All	All	8/28/2014
SIL 05-0006	Extension of Icephobic Paint Inspection Intervals and Introduction of Grace Periods for Scheduled Maintenance	All	All	9/12/2014
SIL 12-0001	Cleaning of Phasebreak™ ESL Icephobic Coating	All	Aircraft with Flight into Known Icing Approval	12/3/2013
SIL 12-0002	Approved Deice Boot Cleaner	All	All	12/19/2013
SIL 20-0001	Weight Off Wheels Simulation	All	Weight Off Wheels Maintenance Procedures	2/11/2014

Document Number	Subject	Effectivity	Applicability	Issue Date
SIL 20-0002	Inspection and Maintenance of Polished Window Frames	Aircraft with Polished Window Frames	Aircraft with Polished Cockpit Window Frames that are Not Protected by a Polyurethane Clear Coat	6/26/2014
SIL 21-0001	NACA Inlet Panel Seal Replacement	All	All	5/28/2014
SIL 21-0002	Gear Driven Compressor Assembly Hose Fittings	EA500 serial numbers (500-) 000001 thru 000262 and 000266 and 000267 when modified per MB 500-21-001	All aircraft equipped with a Gear Driven Compressor Assembly	3/11/2014
SIL 21-0003	Unapproved Parts Notification, Dukes Aerospace Incorporated	All	All	9/4/2014
SIL 21-0004	Gear-Driven Compressor Assembly Leakage	Eclipse 500 serial numbers 000001 thru 000262, 000266, and 000267 when modified per MB 500-21-001. All Eclipse 550 serial numbers.	All aircraft equipped with a Gear-Driven Compressor Assembly	5/5/2015
SIL 21-0005	NACA Inlet Ram Air Flapper Door Bonding Strap Replacement	Aircraft S/N 1 and Up	Post SB 500-99-004	5/26/2016
SIL 22-0001	Autopilot Software Change	(500-) 000001-000300	Autopilot Servos P/N 01299-14-03-01, 01299-24-03-01 and 01299-34-03-01	9/10/2012
SIL 22-0002	Autopilot Servo Installation	All Aircraft	All Aircraft	8/28/2013
SIL 23-0001	Antenna Diverter Strip Replacement	Aircraft Serial Numbers 000001 - 000300	CI 2728-410 GPS/XM/VHF ComDat® Antenna	3/28/2013

Document Number	Subject	Effectivity	Applicability	Issue Date
SIL 23-0002	European Union CPDLC Mandate	All	All	8/27/2014
SIL 24-0002	Aft PDC ECBU Configuration Update	500-000001 thru 500-000262, 500-000266, and 500-000267 when equipped with IFMS 2.07, 2.5, 2.7 or higher. 550-000263 thru 550-000265, 550-000268 thru 550-000280, and 550-000282 and subsequent	All aircraft equipped with 1160-5 Aft Power Distribution Centers	2/28/2014
SIL 24-0003	Main Aircraft Battery Life Expectancy and Unapproved Battery Re-Blocking	All Aircraft	All Aircraft	1/13/2015
SIL 24-0004	Main Aircraft Battery Maintenance and Health Monitoring	All Aircraft	All Aircraft	11/17/2016
SIL 24-0005	Main Aircraft Battery Charging	Eclipse 500 and 550	All Aircraft	11/6/2019
SIL 25-0001	Configuring the Aircraft With Less Than Five Seats	All Aircraft	All Aircraft	6/24/2013
SIL 26-0001	Fire Extinguisher Cartridge Allowable Pressure	(500-) 000001-000300	26-123127-1001 Fire Extinguisher Cartridge	7/18/2013
SIL 28-0001	Alternate Fuel Filler Cap	All Aircraft	All Aircraft	8/12/2015
SIL 30-0001	Ice-Phobic Coating Streaking	(500-) 000001-000300	Aircraft with SB 500-99-004 Incorporated	1/10/2013
SIL 30-0002	Wing/Horizontal Stabilizer De-Ice Boot Repair	All	All	9/2/2014
SIL 30-0003	PPG Windshield Heat Performance	All Aircraft	Aircraft equipped with glass-faced windshields	11/9/2016
SIL 31-0001	Bleed Valve Fail CAS Messages	Aircraft not equipped with Avio IFMS 2.5 or higher	As indicated within SIL	11/25/2013

Document Number	Subject	Effectivity	Applicability	Issue Date
SIL 31-0002	Changing an Aircraft Registration Number	Aircraft with AvioNG 1.3,1.5, 1.7, IFMS 2.0, and IFMS 2.5	Aircraft Registration Number Maintenance Procedures	3/11/2014
SIL 31-0003	MFD Firmware Update for Eclipse 550® MFD Flickering	Aircraft Equipped with 9D-84100-3 MFDs	Aircraft with IFMS 2.7 or Higher	2/12/2016
SIL 31-0004	Sending DSU Data to Service Engineering	All Aircraft	All Aircraft	6/5/2017
SIL 31-0005	iFMS 2.7 and 2.8	All Aircraft	All Aircraft	9/20/2017
SIL 32-0001	Time Limited Maintenance Requirements for Main and Nose Wheels	(500-) 000001-000300	All	3/26/2013
SIL 32-0002	Repair Support for Electromech Actuators	All	Aircraft equipped with Electromech Actuators	12/12/2014
SIL 32-0003	Landing Gear Fail CAS Messages	000001-000260	Aircraft Equipped with Electromach Landing Gear Actuators	9/15/2016
SIL 34-0001	GPS Receiver Support	(500-) 000001-000260	Aircraft Using P/N 13764 Series GPS Receivers	10/30/2013
SIL 34-0002	Navigation Database Issues	Aircraft with IFMS EFIS	Aircraft using Jeppesen Navigation Database Services	2/10/2014
SIL 34-0003	Weather Radar / Radome Compatibility	All	Weather Radar Equipped Aircraft	4/22/2014
SIL 34-0004	Loss of Navigation FMS Message	(500-) 000001 thru 000262, 000266 and 000267	IFMS 2.03, 2.04, and 2.06 Equipped Aircraft	5/6/2014

Document Number	Subject	Effectivity	Applicability	Issue Date
SIL 34-0005	Missing Departures and Runway Transitions on Arrivals in IFMS Navigation Databases	000001 - 000262, 000266 - 000267, 550-0263 - 550-265, 550-0268 - 550-0284	IFMS 2.0, 2.5 and 2.7 Equipped Aircraft	6/19/2014
SIL 34-0006	Availability of Air Data Components	All	All	8/20/2014
SIL 34-0007	Introduction of Improved Pitot / AOA and Pitot / Static Software	All	All Aircraft Certified for Flight into Known Icing (FIKI)	9/12/2014
SIL 34-0008	Standby Display Unit Software Update	All Aircraft	Aircraft Equipped with Standby Display Units	1/13/2015
SIL 34-0009	Setting a Latitude Value in the Standby Display Unit	All Aircraft	Aircraft Equipped with Standby Display Units	1/19/2015
SIL 34-0010	Required Testing of Transponder Pressure Altitude Reporting Equipment	All Aircraft	All Aircraft	3/5/2015
SIL 34-0011	Damaged Pitot/AOA Probe Ram Air Pneumatic Tube	All Aircraft	All Aircraft	12/19/2018
SIL 34-0013	IFMS 2.7.10 EFIS Software Release Notes	Aircraft with IFMS 2.7.8 EFIS Software and GPS 2.10 Software	Aircraft with IFMS 2.7./ 2.8 EFIS Software	7/18/2019
SIL 45-0001	Avio Maintenance Computer Software 2.4.00	All	AMC P/Ns 20-120576-1001 and 20-121925-1001	9/21/2012
SIL 45-0002	DSU Connection Improvement	(500-) 000001-000300	All	10/4/2012
SIL 45-0003	Avio Maintenance Computer Software 2.5.00	All Aircraft	AMC P/Ns 20-120576-1001 and 20-121925-1001	12/4/2014
SIL 45-0004	Alternative Method of Uploading DSU Data	All Aircraft	All Aircraft	12/31/2014
SIL 45-0005	Weight and Balance Update for AMC 2.5.10	All Aircraft	All Aircraft	1/11/2017
SIL 45-0007	Engine Condition Trend Monitoring via Iridium Satellite System	All	Aircraft with IFMS 2.7.8 EFIS Software	3/27/2018

Document Number	Subject	Effectivity	Applicability	Issue Date
SIL 45-0008	Avio Maintenance Computer Aircraft Configuration Page	All Aircraft	Aircraft with IFMS 2.08 or IFMS 2.5.2 EFIS Software and ADS-B.	3/25/2020
SIL 52-0001	Upper Door Gas Strut	(500-) 000001-000300	Replacement Gas Spring Strut P/N 9416K376	2/21/2013
SIL 52-0002	Passenger Door Lock Pin O-Ring Replacement	All Aircraft	All Aircraft	4/26/2019
SIL 56-0001	Windshield Resistive Strip Erosion	(500-) 000001-000300	Aircraft incorporating SB 500-56-002	1/2/2013
SIL 57-0001	Polishing of Wing Tip Nav Light Lenses	All aircraft	All aircraft	9/16/2015
SIL 73-0001	Pulling or Collaring FADEC ECBs with an Engine Running	All Aircraft	All Aircraft	10/22/2015
SIL 76-0001	MB 500-76-001 FADEC Software Upgrade	(500-) 000001-000038, Post SB 500-99-001 and 000039-000262, 000263-000265, 000266, 000267, 000268-000284	All ETT Equipped Aircraft	1/17/2014
SIL 99-0001	Aircraft Removed From Service	(500-) 000024, 000032, 000042, 000103, 000107, 000142, 000172 and 0000199	All	5/6/2013
SIL 99-0002	Suspected Unapproved Parts	All aircraft	Aircraft with parts provided by PMA Sales in Mesa, AZ	7/1/2014
SIL PW600-020	PW610F-A Combustion Chamber Liner Upgrade Commercial Support Program		PW610F-A Engines not incorporating SB 60077 or SB60079 or SB60083	5/13/2014

Service Kits



Document Number	Subject	Effectivity	Applicability	Issue Date
SK 21-0001	NACA Seal Replacement	Eclipse 500 Series	2199041 and 2199042 NACA Inlet Assy.	5/28/2013
SK 21-0002	NACA Seal Replacement	Eclipse 500 Series	2199061 and 2199062 NACA Inlet Assy.	5/28/2013

Customer Pilot Communications (CPC)



Document Number	Subject	Effectivity	Issue Date
500-2007-001	ITT Exceedances while Setting Takeoff Thrust	000001-000250	9/18/2007
500-2007-002	Uncommanded MFD Events	000001 - 000104, 000113 - 000115, 000120, 000123, 000124 pre SB 500-31-007	9/12/2007
500-2007-003	Erroneous Fuel Indications	000001 to 000023 pre SB 500-28-001	9/18/2007
500-2007-004	Tips for starting EA-500 in Cold Weather	000001 and up.	11/20/2007
500-2007-005	Low Oil Pressure Indications	All Aircraft	12/18/2007
500-2008-006	Stabilized Approaches and Proper Braking	All Aircraft	2/27/2008
500-2008-007	Rudder Trim Operation	All Aircraft	4/30/2008
500-2008-008	Pitot / AOA Probes	All Aircraft	4/19/2008
500-2008-009	Prevention of Data Storage Unit (DSU) Failures	All Aircraft	6/10/2008
500-2008-010	Throttle Lever Force	All Aircraft	6/9/2008
500-2008-011	Dual ENG CONTROL FAIL CAS	All Aircraft	6/12/2008
500-2008-012A	Engine Surge Events	All Aircraft	10/10/2008
500-2008-013	AvioNG Anomalies	All Avio NG Aircraft	8/18/2008
500-2008-014	Spectralux GPS	AvioNG Aircraft with Spectralux GPS	9/29/2008
500-2008-015	Battery Depletion During Engine Starts	All Aircraft	11/7/2008
500-2009-016	Distribution Process for AFM Temporary Revisions	All Aircraft	1/28/2009
500-2009-017	Preventing Moisture in Static Lines	All Aircraft	1/23/2009
500-2009-018	8.33 kHz Tuning	All Avio NG Aircraft prior to EFIS 1.5	1/27/2009
500-2017-02-A	Aircraft Computer System Failure Mode	All Aircraft	4/12/2017
500-2017-03	External Stowage Compartment Door	All Aircraft	6/29/2017
500-2019-01	Pitot/AOA Probes Flange Heaters and 20 Minute Pre-Heat	All Aircraft	8/21/2019
550-2017-01	Seat Configuration 5-01 Weight and Balance	All Aircraft	1/11/2017

Customer Technical Communications (CTC)



Document Number	Subject	Effectivity	Issue Date
500-2007-001	Unintended Discharge of Engine Fire Extinguishers	All Delivered Aircraft	10/6/2007
500-2007-003	New Wing De-ice Boots	000001 to 000073	11/27/2007
500-2007-004	Performance and AvioNG Retrofit Activities	S/N 1-38 (Performance) 1 – 104, 113-115, 120, 123 & 124 (AvioNG)	11/26/2007
500-2008-005	Tray Table and Cup Holder Use	All Aircraft	5/16/2008
500-2008-006	Crawling Pixels – Avidyne PFD/MFD	A/C affected by this CTC (S/N 500-000001 to 0000104, 0000113 to 0000115, 0000120, & 0000123 to 0000124 prior to Avio NG Upgrade per Service Bulletin 500-99-002)	6/10/2008
500-2008-007	Prevention of Data Storage Unit (DSU) Failures	All Aircraft	6/10/2008
500-2008-008	Engine Surge Events	All Aircraft	8/18/2008
500-2008-009	AD 2008-19-01; Harco Labs Pitot/AOA Probes	Aircraft with pitot/AOA probes S/N 740000 through 799999	9/11/2008
500-2008-010	Spectralux GPS	AvioNG aircraft with Spectralux GPS	10/3/2008
500-2008-011	Spectralux GPS	AvioNG aircraft with Spectralux GPS	10/24/2008
500-2010-012	Static Port Placard Installation	Serial Number 00001 - up (with FIKI Service Bulletin)	4/14/2008
500-2010-013	Use of Start Pac Model 1400-JR Voltage Reduction Unit	00001 - up	6/4/2010